


IPD3WHTY&IPD3BLKZ


Correct Set up Instruction

step 1



Note :
Counterclockwise rotation
the tool fastening screw.

step 2





Error Set up Instruction


step 1




step 2



A=1PC





M5X20
B=4PCS




C=2PCS


step 3




E=1PC



D=2PCS



TOOL=1PCS



M5X25
F=4PCS